

LEGACY Home Inspections

Presents

Walk-Through Consultation

An Exclusive Presentation for

All Agents in KC Metro

Robert Ladd, CPI Certified Professional Inspector

Goal

Goal

Provide you and your Buyer's with a sense of peace in writing a contract utilizing Box 3.









Discolored Shingles





Shingle Waves





Thick Edges



Darkened Shingles



- Darkened Shingles
- Waves



- Darkened Shingles
- Waves
- Thick edges





Discolored Shingles



Discolored Shingles

Asphalt Bleed Through



Discolored Shingles

Asphalt Bleed Through



Discolored Shingles



Discolored Shingles

Asphalt Bleed Through



Discolored Shingles

Algae



Discolored Shingles



Shingles Waves







Thick Edges



Shingles Waves





Is that stucco synthetic?





1.Thumb Test



- 1.Thumb Test
- 2.Ring Test



- 1.Thumb Test
- 2.Ring Test
- 3.Insulation Test





Broken Seal



Broken Seal





Broken Seal







Broken Seal





wiseGEEK



Cool Word for the Day

Cool Word for the Day

Argon Gas





What Are Those Dark Spots



Mud/Resin Jacking



Before





Before

After

Is mud-jacking cost-effective?

About 1/3 the cost of replacement





How Old?

The age is ALWAYS

The age is ALWAYS in the Serial Number







HOME

WHAT MAKES US DIFFERENT

WHAT WE INSPECT

PRICING

BOOK AN INSPECTION

MORE ...



We're the Largest Home Inspection Company in Kansas City

We have 15 certified inspectors performing over 3,000 inspections per year. The average



HOME

WHAT MAKES US DIFFERENT

WHAT WE INSPECT

PRICING


BOOK AN INSPECTION

MORE ...



We're the Largest Home Inspection Company in Kansas City

We have 15 certified inspectors performing over 3,000 inspections per year. The average



Building Intelligence Center


Your #1 resource for determing the date of manufacture or age of HVAC & Water Heater equipment.

Home

HVAC -PRODUCTION DATE/AGE



How to determine the date of manufacture, production or age of your furnace, air conditioner, heat pump, boiler, evaporator, cooler or other HVAC equipment



ON

ce

Data turer Info ge


GE INFO

Donate


Search × d by Google**

cent
s
leating
oxide

shut down Adirondack-Aire	Franklin Electrick	1 Old 15
ADP	Fraser-Johnston	Precision
Home Advantage	Friedrich	Premier
Home Advantage Jan 2014 AEC	Frigidaire	
sure switch	Fujitsu	
ron natural water boilers Aeroflo	-	Q
mers when Airco	G	
Airedale		Quietside
Decline to Fall and	Gaffers & Sattler	
(Thu, 09 Air-Ease Johnson	General Electric - (GE)	R
be frame of bscription List Aire-Flo	Geocomfort	
Go		Raypac Motivair
Web Site Airquest	Geo-Flo	Red T
Air Star	Geosource	Remington
AirTemp	Gibson	REPCO
Airtherm	Glowcore	Republic
Airwell-Fedders	GmC	Retroaire
Allied Commercial	Goetti	Reznor
AllStyle	Goodman	Rheem
Alton	Governaire	Richmond
Amana	Grandaire	Riello
American Best	Green Colonial	Rinnai
American Furnace	Grimsby	RiteTemp
American Radiator	0	Riva
American Standard		Robur
Anthes	Н	Rush Air
Applied Air		Ruud
Aqua Products	Haier	Rupp
Aquazone	Hallmark	
ARCOAIRE	Hamilton	s
Arctic Circle	Hamilton Electric	
ARGO	H.B. Smith	Samsung
ARKLA	Heat Controller	Sanyo
Armstrong	Heatmaster	Saturn
Armstrong Air	Heil	Sears
Aspen	Heil-Quaker	Semco
Avenger	HermanNelson	Series 16
Atherion	Hot Dawg	Sharp




Water Heater Data Plate














Complete Combustion





Potential Cracked Heat Exchanger



Service Schedule

Air Conditioner 12-15 years

- Air Conditioner 12-15 years
- Furnace 15-20 years

Air Conditioner 12-15 years

• Furnace 15-20 years

Water Heater 8-10 Years






Asbestos Floor Tiles?



Asbestos Floor Tiles?

8" Squares










Pex





Pex

Polybutylene







PB2110














Copper Good

Crimp

Fitting








Copper Good

Crimp

Fitting







HOME INSPECTIONS

Aluminum
Not so much





HOME INSPECTIONS

Exterior Corrosion at Brass Fitting





Zurn fitting Model F1807

What is the most commonly asked safety-related question?

What is the most commonly asked safety-related question?

Is my electric panel in good shape?



Electric Panel



STAB-LOK



Zinsco



Bulldog Pushmatic



STAB-LOK



STAB-LOK



Pushmatic







Pushmatic



Zinsco



Digital Thermometer



Breaker Temperature Reading



Mini Thermal Imaging Camera



What they see



What they see



What we see



What they see



What we see

Carpet with 40% moisture






What they see





What they see




What we See






What they see



What we See

Ceiling with 53% water














Termites













Boston Marathon Bomber





Foundations





Vertical







Vertical

Diagonal









Vertical

Diagonal

Horizontal





Horizontal





Horizontal

Serious Defect





Horizontal

- Serious Defect
- Pressure from Outside the Wall





Horizontal

- Serious Defect
- Pressure from Outside the Wall
- Hydrostatic Pressure





Horizontal

- Serious Defect
- Pressure from Outside the Wall
- Hydrostatic Pressure
- Structural Engineer





Lateral Brace



- Lateral Brace
- Deadman Anchors




- Lateral Brace
- Deadman Anchors
- Epoxy Injections




- Lateral Brace
- Deadman Anchors
- Epoxy Injections
- Carbon Fiber Strips



- Lateral Brace
- Deadman Anchors
- Epoxy Injections
- Carbon Fiber Strips
- Piers






Lateral Braces







Deadman Anchors




Deadman Anchors



Deadman Anchors



Deadman Anchors



Deadman Anchors





Carbon Fiber Strips





Epoxy Injection





Evidence of Piers



Helical Piers






Cold Pour






Efflorescence







Dry Basement System



Dry Basement System


What are the signs that a house has settled?



Exterior Cracks








Exterior Cracks



Exterior Cracks




Exterior Cracks




Chimney Separation



Exterior Cracks



Exterior Cracks




Chimney Separation



Mudjacking



Exterior Cracks



Exterior Cracks




Chimney Separation



Mudjacking



Exterior Cracks



Exterior Cracks



Chimney Separation



Mudjacking



Cracked Floor Tiles

With Any Structural Repairs...

With Any Structural Repairs... The most important question to ask...

With Any Structural Repairs...

The most important question to ask...

Is there a Transferrable Warranty?







Lumberyard Mold

✓ Over 1000 strains

- ✓ Over 1000 strains
- ✓ Only one is Toxigenic

- ✓ Over 1000 strains
- ✓ Only one is Toxigenic
- **✓ Black Mold**

- ✓ Over 1000 strains
- ✓ Only one is Toxigenic
- √ Black Mold

Funny thing about Black Mold...

- ✓ Over 1000 strains
- ✓ Only one is Toxigenic
- √ Black Mold

Funny thing about Black Mold... Its Green



Stachybotrys Chartarum

• Warm

- Warm
- Wet

- Warm
- Wet
- Dark

- Warm
- Wet
- Dark
- Humid

- Warm
- Wet
- Dark
- Humid
- Extended Period of Time

• If the mold is less than 10 feet square

- If the mold is less than 10 feet square
- Don't paint over it, remove it

- If the mold is less than 10 feet square
- Don't paint over it, remove it
- Wear N-95 Mask/Gloves/Goggles

- If the mold is less than 10 feet square
- Don't paint over it, remove it
- Wear N-95 Mask/Gloves/Goggles
- 90/10 solution of ammonia or bleach

(Do not mix cleaners)

- If the mold is less than 10 feet square
- Don't paint over it, remove it
- Wear N-95 Mask/Gloves/Goggles
- 90/10 solution of ammonia or bleach (Do not mix cleaners)
- Clean with sponge

- If the mold is less than 10 feet square
- Don't paint over it, remove it
- Wear N-95 Mask/Gloves/Goggles
- 90/10 solution of ammonia or bleach (Do not mix cleaners)
- Clean with sponge
- Air dry the surface (fan)

Cool Word for the Day

Stachybotrys Chartarum











Eastern Subterranean Termite






Shelter Tubes













Three Pounds Per Year





Termites Eat Drywall





Termites Eat Styrofoam

















Termite Damage





Termite Damage



Woodrot





Termite Damage (with grain)



Woodrot (across grain)



Where are termites most likely to enter a home?





Termite Treatment on Front Porch





Open Porch During Construction



Termites are not the only wood destroying insects in Kansas City



















Carpenter Bees









Carpenter Bees



Bumble Bees











Powder Post Beetle











Carpenter Ants









Lathe Blemish











Swarming Ants










Swarming Termites










Ants





Takes 2-4 years to produce Swarmers





Ant



Termite

Good Luck to all members of the Agents in KC Metro Family

And Thank You for allowing me to be a small part of your success!